



GNSS Firmware v4.8p2

Release Notes

November 2021

©Copyright Topcon Positioning Systems, Inc. 2020

All contents in this document are copyrighted by Topcon. All rights reserved. The information contained herein may not be used, accessed, copied, stored, displayed, sold, modified, published, or distributed, or otherwise reproduced without express written consent from Topcon.

Table of Contents

SUPPORTED PRODUCTS	3
SYSTEMS	3
OEM BOARDS.....	3
FEATURES AND CHANGES	3
FEATURES AND CHANGES FROM PREVIOUS RELEASES	4

Supported Products

Systems

- Topcon HiPer SR, GR-5¹, HiPer V², HiPer II, GRS-1, Net-G3A, MR-1, MC-i3, and MC-i4
- Sokkia GSX2, GCX2³, GRX2, GRX1, and GHX2 (Mesa RTK)

OEM Boards

- B110, OEM-1, Euro 112PII

Features and Changes

- Supported ObsFlags(2) field in BINEX output (all products)
- New support for controlling HTTPS to improve security and stability (Net-G3A)
- Updated antenna database
- Improve satellite tracking in difficult conditions and in presence of moderate interference/jamming (manual calibration required)

¹ GR-5 with Vanguard technology now supported by FW 5.1p1 and later.

² GR-5 (without Vanguard technology), HiPer II, HiPer V, Net-G3A, MR-1, and GRS-1 sales have been discontinued. Service and technical support is still available for these products.

³ Sokkia GRX1, GCX2, GRX2 sales have been discontinued. Service and technical support is still available for this product.

Features and Changes from Previous Releases

Changes introduced in 4.8p1 (Net-G3A only)

- Support ObsFlags(2) field in BINEX output

Changes introduced in 4.8

- Incorporates all changes from previous releases (4.7p6, 4.7p7, 4.7p8 and 4.7p10)
- Tuning of DION, Velocity filters, VISOR convergence, Satellite acquisition and tracking algorithms.
- Tuning of default values for positioning engine:
 - minimum SNR values for GPS and GLONASS L2 signals in RTK changed to 15.
 - PDOP mask changed to 20
 - Minimum number of satellites changed to 6
 - Ambiguity fixing level set to extralow
 - Doppler smoothing filter parameter extended to 100 Hz
 - Default value for pos/dion/switch changed to on.
- Message improvements:
 - New extended [Lh] message added to support all constellations (based on original [LH] message)
 - Extended [ha] message to include HRMS and PRMS values
 - Fixed output of [LE], [LA] and [WO] messages
 - Fixed output of wsmcnt parameter
- Increased acquisition of GPS L2C signal.
- Performance using 100 Hz position update rate improved (applies to specific configurations with OEM boards only)
- Support for Satellite Status Code 61
- Enhanced satellite reacquisition in cases of antenna shadowing.
- Fixed reporting of battery information (HiPer SR only).
- Updated Antenna database
- Fixed UDP data transfer protocol (Net-G3A)
- Improved logic to update base data when reference station changed
- Fixed issue with loss of RTK fixed solution after correction type change when using AIM mode.

Changes introduced in 4.7p10

- Fix for BINEX output after GPS week rollover (Net-G3A only)
- Improved firmware performance during leap second and GPS week rollover events.

Changes introduced in 4.7p8⁴ (released for Topcon HiPer SR, B110 OEM, Sokkia GSX2, Sokkia GCX2 only)

- Optimized internal memory usage and processor loading for B110 based receivers
- Added protections during firmware installation which restricts installation of firmware on incompatible B110 based hardware.⁵

⁴ Please see 4.7p8 Release Notes for complete information and compatibility notes.

⁵ If an incompatibility between B110 based firmware and hardware is identified during installation, the process will be stopped automatically. A power reset will return the receiver to its previous state.

Changes introduced in 4.7p7⁶ (released for Topcon BX10 OEM, MC-i4 (BX10), MC-i3 only)

- Improved data backup to memory during receiver reset (HiPer V & GRX2). Also requires installation of Mainboard Firmware v2.3.
- Optimized internal memory usage and processor loading for BX10 based receivers.
- Added protections during firmware installation which restricts installation of firmware on incompatible BX10 based hardware.⁷

Changes introduced in 4.7p6 (released for Topcon OEM-1, MR-1, Euro112PII, Net-G3A only)

- Improved firmware performance during Leap Second and GPS Week Rollover events.
- DION improvements to fix behavior when NTRIP corrections received
- RMS error improvements in Stand-alone and Code Differential engines, as well as for velocities in RTK mode.
- Output of full covariance matrix (SP, SV, AP messages) is enabled for all solution modes.
- Added support for use of mixture of corrections for GPS L2C and GPS P2 simultaneously in RTK.
- Fixed "QZSS L2C quarter cycle" issue when working with non-Topcon bases.
- Improved GLONASS tracking when not visible parameter status is changed.
- PI message was updated to include mmGPS solution indicators.
- New antenna data base version 2.3.6 has been supported.
- New classes are introduced for Trimble, Novatel and Sokkia receivers in order to better handle for GLONASS biases in positioning solution:
 - TPS - for all Topcon receivers
 - JPS - for Javad receivers
 - ASHTECH - for Ashtech receivers
 - SOK - for legacy Sokkia receivers
 - SKA - for Topcon/Sokkia receivers - new class
 - SEPT - for Septentrio receivers
 - MAGELLAN - for Magellan receivers
 - NOV - for Novatel with old firmware (approximately - prior September 2016)
 - 2NOV - for Novatel with new firmware (approximately - after September 2016) - new class
 - LEICA - for Leica receivers
 - TRIMBLE - for Trimble receivers with old firmware (approximately - older than 5.11 of 2016)
 - 2TRIMBLE - for Trimble receivers with new firmware (approximately - 5.11 of 2016 and newer) - new class
 - OTHER - for other receivers
 - UNKNOWN - if receiver is unknown

⁶ Please see 4.7p7 Release Notes for complete information and compatibility notes.

⁷ If an incompatibility between BX10 based firmware and hardware is identified during installation, the process will be stopped automatically. A power reset will return the receiver to its previous state.