



GNSS Firmware v5.2.6

Release Notes

June 2020

©Copyright Topcon Positioning Systems, Inc. 2020.

All contents in this document are copyrighted by Topcon. All rights reserved. The information contained herein may not be used, accessed, copied, stored, displayed, sold, modified, published, or distributed, or otherwise reproduced without express written consent from Topcon.

Table of Contents

- SUPPORTED PRODUCTS 3**
 - SYSTEMS 3
 - OEM 3
- FEATURES AND CHANGES 3**

Supported Products

Systems

- Topcon Net-G5, HiPer HR, MR-2, GR-5 (with Vanguard technology)
- Sokkia GNR5, GCX3

OEM

- Topcon B111, B125, B210

Features and Changes

5.2.6

- Corrected $\frac{1}{2}$ cycle biases for Galileo E5(a+b) carrier phase measurements
- Corrected missing \$ character in GST message when antenna is disconnected from receiver
- Fixed power button behavior in exception mode (Net-G5)
- Corrected behavior of RTCMv3 output option